

## HISTORIC AMERICAN BUILDINGS SURVEY

### INDEX TO PHOTOGRAPHS

SALUBRIA  
Salubria Lane  
Stevensburg vicinity  
Culpeper County  
Virginia

HABS VA-1430

### INDEX TO BLACK AND WHITE PHOTOGRAPHS

Douglas J Harnsberger, photographer, 2010

VA-1430-1	South Elevation
VA-1430-2	North Elevation
VA-1430-3	West Elevation (note entrance to basement )
VA-1430-4	East Elevation
VA-1430-5	Detail view of the east elevation to show the double-hung wood sash glazed with nine-over-nine lights on the first-floor level and the window to the basement; both window openings have segmental arches
VA-1430-6	Interior view, view looking north in the center hall
VA-1430-7	Interior view, close view looking to the arched opening for the enclosed, winding stair
VA-1430-8	Interior view, northwest room, view looking southwest to the corner fireplace
VA-1430-9	Interior view, northeast room, view looking southeast to the corner fireplace; note the built-in cabinet in the south wall
VA-1430-10	Interior view, second floor, view looking northeast to show the east side of the floor
VA-1430-11	General view looking to the north elevation

SALUBRIA  
HABS VA-1430  
INDEX TO PHOTOGRAPHS

VA-1430-12	Detail view to show paneled door and molded trim
VA-1430-13	Detail view, west elevation to show the enclosed entrance to the basement; note the hipped roof and window opening beneath a segmental arch, features in keeping with the main house
VA-1430-14	View looking to the east elevation
VA-1430-15	Interior view, second floor, view looking east
VA-1430-16	Interior view, second floor, view looking north
VA-1430-17	Interior view, second floor, fireplace